

Hexam Road, Reading - tree survey data

Tree no	Location	Species	Ht	Canopy ht	Dia at 1.5	N	E	S	W	Age Class	BSCat	Physiological	Structural	RLC	Work recs
T1	Frontage, east of main gate	Norway maple	9	2.5	480	4	4	4	4	EMa	A1,2	Good	Good. Balanced form	40+	Retain & protect.
T2	Frontage, east of main gate	Macrocarpa	8	0	530	3	2	5	2	EMa	C2,3	Fair	Fair to poor. Compression fork at c.1m, 2 even leaders	20+	Fell for proposal
T3	Frontage, east of main gate	Macrocarpa	9	0	800	3	5	3	5	EMa	C2,3	Poor	Poor. multiple atems from base. congested crown	20+	Fell for proposal
T4	By wall	Hornbeam	8	1	320					EMa	C3	Poor	Poor. layered secondary stem to east.		Fell for proposal
T5	Rear fence	Cherry	9	3.5	390	2	4	2	2	EMa	C3	Fair to poor. Sparse. Heavy ivy colonisation.	Fair. Slight lean to east.	20+	Fell for proposal
T6	SW corner	Norway maple	12	3.5	590	5	4	4	4	EMa	A1,2	Good	Good. Balanced form	40+	Retain & protect.
T7	SW corner	Norway maple	10	2.5	310	2	2	5	5	EMa	B1,2	Good	Fair	40+	Retain & protect.
T8	West boundary	Norway maple	12	2.5	550	5	4	5	6	EMa	B1,2	Good	Good to fair	40+	Retain & protect.
T9	West boundary	Norway maple	9	2	380	4	2	3	4	EMa	C3	Fair to poor. Suppressed. Sparse on s side, moderate deadwood present.	Fair. Slight lean to NE	20+	Retain & protect.
T10	West boundary	Cherry	11	2.5	460	4	4	3	4	Ma	B1,2,3	Fair. Slightly congested crown. Suckering.	Fair. Fork at 3m with inclusion but fairly balanced	20+	Retain & protect.
T11	West boundary	Weeping willow	6	0	210	2.5	2.5	2.5	2.5	Y	B2	Good	Good to fair. Sprouting from fork at 1.5 - usual for spp.	40+	Retain & protect.
T12	West boundary	Norway maple	12	3.5	490	4	4	4	4	EMa	A1,2	Good	Good. Balanced form	40+	Retain & protect.
T13	NW corner	Liquidambar	3	1	180	1.5	1.5	1.5	1.5	Y	B1	Good	Good	40+	Fell for proposal
T14	N boundary west of gate	Cypress	4	0	250	1.5	1.5	1.5	1.5	EMa	B2	Fair to good	Fair to good	20+	Fell for proposal
T15	N boundary west of gate	Cypress	4	0	250	1.5	1.5	1.5	1.5	EMa	B2	Fair to good	Fair to good	20+	Fell for proposal
T16	N boundary west of gate	Cypress	4	0	210	1.5	1.5	1.5	1.5	EMa	B2	Fair to good	Fair to good	20+	Fell for proposal
T17	N boundary west of gate	Cypress	2	0	250	1	1	1	1	EMa	C2	Fair to good	Fair to good	20+	Fell for proposal
T18	N boundary west of gate	Cypress	4	0	250	1.5	1.5	1.5	1.5	EMa	B2	Fair to good	Fair to good	20+	Fell for proposal
T19	N boundary west of gate	Cypress	4	0	200	1.5	1.5	1.5	1.5	EMa	U	Dead	Dead	N/A	Fell due to poor condition
T20	N boundary west of gate	Golden cypress	4	0	250	1.5	1.5	1.5	1.5	EMa	B2	Good to fair	Fair to good	20+	Fell for proposal
T21	N boundary west of gate	Lawsons cypress	5	0	220	1	1	1	1	Y	C2	Fair to poor	Poor	<10	Fell, both for proposal and poor structural form
T22	SE corner	Weeping willow	9	1	650	5	5	5	5	Ma	U	Fair	Poor. Large decay section on mid main stem	<10	Removed at demolition stage due to poor condition
T23	SE corner	Corkscrew hazel	3	2	200	2	2	2	2	Y	C2	Fair	Fair	20+	Fell for proposal
T24	SE corner	Cherry	9	2	280	2	2	2	2	EMa	C2,3	Fair	Fair to poor. previously reduced. damage and split to southern lateral.		Fell for proposal
T25	SE corner	Norway maple	11	3.5	550	4	4	4	4	EMa	B2,3	Fair to poor. Sparse. Heavy ivy colonisation.	Fair	10+	Fell for proposal
T26	SE corner	Beech	6	1	260	1.2	1.5	1.5	1.2	EMa	C2,3	Fair	Fair compression union at fork at 3.5m	20+	Fell for proposal
T27	SE corner	Cherry	6	1	260	1.2	1.2	1.2	1.2	EMa	C2,3	Fair	Fair	20+	Fell for proposal
T28	SE corner	Purple plum	6	2	250	2	2	2	2	EMa	C2,3	Poor	Poor	<10	Fell for proposal
T29	East of gate	Lawsons cypress	5	0	150	1	1	1	1	Y	C3	Fair	Poor: twin stem form low compression fork	10+	Fell for proposal
T30	Centre of site, south of building	Robinia	13	2.5	350e	2.5	2.5	2.5	2.5	EMA	C2	Good.	Poor: submissive compression fork at c.2.5m, likelihood of tear out at this point.	10+	Removed at demolition stage due to conflict with operations