



Window frame resin repairs training piece. Maximises retention of original fabric.
Thick joints reduce risk of failure at joint



Window frame resin repairs training piece. Maximises retention of original fabric.
Thick joints reduces risk of failure at joint.





1.

2.

Timber for replacement work: paint finish gloss white

1. Sills: Iroko
2. Frames: sound sections salvaged from window frames too damaged to repair or Iroko



Paint build up on new or stripped back timber:

Anti-clockwise from top right : bare wood, primer, undercoats, top coat. White 0000-N BS 00E55



1.

2.

Replacement rainwater goods: gloss black

1. Alumasc APEX Cast Iron for replacement of components within a drop
2. Alumasc Aluminium proposed only where full drop to be replaced.



APEX Cast Iron



Alumasc Aluminium



Guttering: 1. APEX Cast Iron – smooth finish

2. Alumasc Aluminium shows textured finish but smooth available and proposed to match cast iron



Sample of re-pointing using Morestead sand with NHL 3.5

