

Drainage Investigation Report

Auger Ref:

103981.2.ICC



Job Information

Client	Sedgwick
Client ref	8845893
Visit date	09/04/2020
Report date	09/04/2020

Job Summary

- ✓ CCTV survey undertaken. [Read more.](#)
- ✓ No drainage defects found. [Read more.](#)



Job Information

Overview

Brief

Auger were commissioned by Sedgwick to undertake a CCTV inspection of the underground drainage within the area of concern at the property.

Findings

Drain Survey

Line 1 - LWA SW MH upstream past boundary

Our survey of line 1 revealed that there were no defects which could be allowing the escape of water. This was noted to be an LWA shared line.

Line 2 - LWA SW MH downstream

Our survey of line 2 revealed a collapse at 2.5m d/s of the manhole. This is an LWA shared line and we would advise that they are contacted to resolve this issue.

Line 3 - LWA FW MH2 upstream past boundary

Our survey of line 3 revealed that there were no defects which could be allowing the escape of water. This was noted to be an LWA shared line.

Line 4 - LWA FW MH2 downstream past boundary

Our survey of line 4 revealed that the LWA mainline was blocked and backing up. We would advise that the customer contacts the LWA to rectify the issues to this line.

Line 5 - RWP1 downstream to LWA SW MH

Our survey of line 5 revealed that there were no defects which could be allowing the escape of water. This line was seen to be free flowing and serviceable.

Line 6 - RWP2 downstream to LWA SW MH

Our survey of line 6 revealed that there were no defects which could be allowing the escape of water. This line was seen to be free flowing and serviceable.

Recommendations

Contact LWA

Our investigations revealed that there is an issue in the local water authority (LWA) section of pipework. We would recommend that the customer contact their LWA in order to further investigate and resolve the issue.

Other Photos


Fig 2.1: LWA SW MH




Fig 2.2: LWA FW MH



Fig 2.3: RWP2







FRONT OF PROPERTY

This drawing should be used for diagrammatic purposes only. Auger are not responsible or liable for any 3rd party works undertaken using the details outlined in this drawing. Confirmation of the drainage configuration can only be confirmed by excavation or detailed technical survey.

LEGEND

	= Manhole		= Blockage		= Lines not camera surveyed		= Steps		= Trial hole		= Shrubs/bush
	= Inspection Chamber		= syp/w/c		= Lines camera surveyed		= Borehole		= Hedge		= Tree
	= Inspection Pot		= wg/fwg		= Assumed water mains feed		= gate / door		= Direction of flow		
			= rwg		= Walls						
			= rwp		= Fences						
					= Building Outline						