

Project Name: Katesgrove School Simmonds Building, Reading
E04948

Repairs to Timber Windows and External Fabric - Phase 2

Condition Survey photos referenced to the Schedule of Works

Schedule of Works

2.2.4 North Elevation 2 W3



2.2.4 W3



2.2.9 - .33, 2.2.55 - .59 East Elevation 1 Central Gable windows



2.2.9 W4



2.2.9 W4 (lower)



2.2.14 W4 (upper)



2.2.19 W5 (lower)



2.2.24 W5 (upper)



2.2.30 W6 (upper)



2.2.37 East Elevation 1 W7



2.2.37 W7



2.2.50 North Elevation 2 W8




2.2.55 East Elevation 1 W9 & W10



2.2.55 W9



2.2.55 W10



2.2.60 East Elevation 1 W11



2.2.65 North Elevation 2 W18 & 2.2.70 W19



2.2.65 W18



2.2.75 East Elevation 1 W20



2.2.80 North Elevation 2 W21



2.2.85 South Elevation 1 W22



2.4.4 East Elevation 1 Brickwork



2.4.6 - .9 East Elevation 1 / North Elevation 2 Brickwork



2.5.2 East Elevation 1 Downpipes



2.5.3 Downpipes



2.5.5 - .10 Elevation 1 / North Elevation 2 Downpipes



2.5.10 East Elevation 1 Downpipes

