



GEOSHIELD Verification Report



OVERVIEW PHOTOS



Overview A/B - 4/7

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



OVERVIEW PHOTOS



Opposing end view

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA: A/B - 4/7

RESTRICTIONS AND LIMITATIONS:

All applications were available for Verification

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA:

N/A

RESTRICTIONS AND LIMITATIONS:

No limitations or restrictions

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE



LOCATION/GRID LINE: 5-A

NOTES:

Columns near Edge , detailed to specification

Hydroprufe 9000 linked to edge via GR girth tape and application of Hydroprufe LG to

Columns



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE



Overview (foreground) of detailed column

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report





VERIFICATION ITEM TWO

LOCATION/GRID LINE: 4A

NOTES: Tear in membrane caused by steel fixers dragging

Steels across surface , before and after pictures shown below I.e

Tear repaired during visit



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM TWO



Overview area of repairs required in membrane

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report





VERIFICATION ITEM THREE

LOCATION/GRID LINE: A-B - 6-7

NOTES: This area waits detailing tape on edge (outer wall A)

and columns , to complete installation of membrane



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed


Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM THREE



Overview outstanding area to be completed

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



REMEDIATION LOG

Date	Nr	Remediation Description	Y/N
20th Mar	001	No remediation items	✓
20th Mar	001	Protection board still to fix	✓
23rd Mar	002	300mm detailing tape overlaid to edge beams and membrane	✓
23rd Mar	002	Column and edge beam detailing sealed to specification	✓
23rd Mar	002	Pipe penetrations detailed to specification	✓
3rd Apr	003	Columns and edge detailing 5A complete	✓
3rd Apr	003	Repairs in membrane 4A	✓
3rd Apr	003	Outstanding detailing to columns and edge A/B -6/7	


GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



ADDITIONAL PHOTOS



Pipe penetration complete

Click to set image

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



GAS MEMBRANE TESTING

VISUAL:

YES



NO



SMOKE TEST:

YES



NO



COMPRESSED AIR:

YES



NO



DILECTIC

YES



NO



DESTRUCTIVE:

YES



NO



YES



NO



OTHER:

GRID LINE:

Area: A/H - 1/3+



GRID LINE:

Area A/H 1/4



GRID LINE:

Area A/B-4/7



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



VERIFICATION SUMMARY

Third visit , some rips and tears in membrane identified , some outstanding to

Complete remediations , other areas remediations complete.

All installed to BS8485 and verified to CIRIA 735

Advised operators and site management to take care to protect membrane ,

Although saying this they did leave the protection matting off for the benefit

of verification temporarily

GEOSHIELD SIGNITURE:

DATE: 3rd April 2017

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



PROJECT REFERENCE: GEO1001700/KC/P

PROJECT: Porcelenosa: Kenwood Construction

PROJECT ADDRESS: 21 Rose Kiln Lane

Reading

RG1 6SP

MEMBRANE SPECIFICATION: Gas membrane to specification BS8485 2015

Installed to CIRIA 735

Hydroprufe 9000

Hydroprufe 8000

Dual Tape

Girth Tape

Foil backed detailing tape

Hydroprufe LG Liquid Gas Membrane

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



MEMBRANE SPECIFICATION:

DESIGN DETAILS:

31363/5002/003 C1 Foundations and ground floor plan

31363/5002/020 C2 Substructure Sections

365001 Rev A

365002 Rev A

365003 Rev A

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



SURVEYOR:

Chris Kynman

VERIFICATION COMPANY:

GeoShield Limited

Hoyle Mill Road

Kinsley

West Yorkshire

WF9 5JB

CONTACT NUMBER:

07387 373 167

EMAIL ADDRESS:

Chris.kynman@geoshield.co.uk

ORDER NUMBER:

PER VISIT: YES:

☐

NO:

☐

PROJECT: YES:



NO:

☐

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



CLIENT DETAILS

CLIENT CONTACT: Stephen Gatehouse

CONTACTS ROLE: Project Manager

MOBILE PHONE: 07887983302 / 01553 776543

EMAIL ADDRESS: Stephengatehouse@chalcroft.co.uk

CLIENT CONTACT:

CONTACTS ROLE:

MOBILE PHONE:

EMAIL ADDRESS

NOTES:

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



APPLICATION TEAM LEADERS

APPLICATOR NAME: Tony Groves: Foreman

COMPANY: Nick Kenward Construction Limited

APPLICATOR TEL: 07730 575862

APPLICATOR EMAIL:

APPLICATOR NAME: Frank Holman

COMPANY: Nick Kenward Construction Limited

APPLICATOR TEL: 07917 688078

APPLICATOR EMAIL:

NOTES:

NOTES:

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



AREA SURVEYED: Wall perimeters A , 9 , 1 & H

SITE CONDITIONS:

WEATHER: Cloudy

TEMPERATURE: 14C

MEMBRANE TEMPERATURE: N/A

RELATIVE HUMIDITY: 63%

TIME: 1.30pm - 2.30pm REPORT NUMBER: 004

DATE: 10th April 2017

ACCOMPANIED Stephen Gatehouse

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



OVERVIEW PHOTOS



Overview wall 1

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



OVERVIEW PHOTOS



Wall 1 , viewed from corner of intersection with wall A

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA: Wall perimeters A , 9 , 1 & H

RESTRICTIONS AND LIMITATIONS:

All applications were available for Verification

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA:

N/A

RESTRICTIONS AND LIMITATIONS:

No limitations or restrictions

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE

LOCATION/GRID LINE: Wall 1

NOTES: Two views showing primed wall 1 ready for application of

Membrane



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE



Overview primed wall 1

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM TWO

LOCATION/GRID LINE: Wall 1 , near corner of wall A ,

NOTES: Photo 1 incorrectly applied GR detailing(remediation)

Tape to wall perimeter

Photo 2 : incorrect tape being removed



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM TWO



Overview of incorrectly applied remediation/detailing tape

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM THREE

LOCATION/GRID LINE: Wall 1 near corner wall A

NOTES: Two views showing progress of Hydroprufe 8000

application , (after the incorrect tape had been removed)



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM THREE



Overview first section of Hydroprufe 8000 application

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



REMEDIATION LOG

Date	Nr	Remediation Description	Y/N
20th Mar	001	No remediation items	✓
20th Mar	001	Protection board still to fix	✓
23rd Mar	002	300mm detailing tape overlaid to edge beams and membrane	✓
23rd Mar	002	Column and edge beam detailing sealed to specification	✓
23rd Mar	002	Pipe penetrations detailed to specification	✓
3rd Apr	003	Columns and edge detailing 5A complete	✓
3rd Apr	003	Repairs in membrane 4A	✓
3rd Apr	003	Outstanding detailing to columns and edge A/B -6/7	✓
10th Apr	004	Wall perimeters primed A, H , 1 & 9	✓
10th Apr	004	Incorrect application of detailing/ remedation tape	✓
10th Apr	004	Correct application of Hydroprufe 8000 on perimeter	✓

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



ADDITIONAL PHOTOS



Hydroorufe 8000



Correct Application



Incorrect product



Incorrect application

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



GAS MEMBRANE TESTING

VISUAL:

YES



NO



SMOKE TEST:

YES



NO



COMPRESSED AIR:

YES



NO



DILECTIC

YES



NO



DESTRUCTIVE:

YES



NO



YES



NO



OTHER:

GRID LINE:

Area: A/H - 1/3+



GRID LINE:

Area A/H 1/4



GRID LINE:

Area A/B-4/7



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



VERIFICATION SUMMARY

Fourth visit , mainly discussion and demonstration of the application of

Correct product and method for wall perimeters , application in progress .

Site management initially believed that a liquid gas membrane would suffice

For the perimeter , after consultation and discussion , confirmed the correct

Membrane for the perimeter I.e Hydroprufe 8000 , to be applied

All installed to BS8485 and verified to CIRIA 735

GEOSHIELD SIGNITURE:

DATE: 10th April 2017

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



PROJECT REFERENCE: GEO1001700/KC/P

PROJECT: Porcelenosa: Kenwood Construction

PROJECT ADDRESS: 21 Rose Kiln Lane

Reading

RG1 6SP

MEMBRANE SPECIFICATION: Gas membrane to specification BS8485 2015

Installed to CIRIA 735

Hydroprufe 9000

Hydroprufe 8000

Dual Tape

Girth Tape

Foil backed detailing tape

Hydroprufe LG Liquid Gas Membrane

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



MEMBRANE SPECIFICATION:

DESIGN DETAILS:

31363/5002/003 C1 Foundations and ground floor plan

31363/5002/020 C2 Substructure Sections

365001 Rev A

365002 Rev A

365003 Rev A

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



SURVEYOR:

Chris Kynman

VERIFICATION COMPANY:

GeoShield Limited

Hoyle Mill Road

Kinsley

West Yorkshire

WF9 5JB

CONTACT NUMBER:

07387 373 167

EMAIL ADDRESS:

Chris.kynman@geoshield.co.uk

ORDER NUMBER:

PER VISIT: YES:

☐

NO:

☐

PROJECT: YES:



NO:

☐

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



CLIENT DETAILS

CLIENT CONTACT: Stephen Gatehouse

CONTACTS ROLE: Project Manager

MOBILE PHONE: 07887983302 / 01553 776543

EMAIL ADDRESS: Stephengatehouse@chalcroft.co.uk

CLIENT CONTACT:

CONTACTS ROLE:

MOBILE PHONE:

EMAIL ADDRESS

NOTES:

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



APPLICATION TEAM LEADERS

APPLICATOR NAME: Tony Groves: Foreman

COMPANY: Nick Kenward Construction Limited

APPLICATOR TEL: 07730 575862

APPLICATOR EMAIL:

APPLICATOR NAME: Frank Holman

COMPANY: Nick Kenward Construction Limited

APPLICATOR TEL: 07917 688078

APPLICATOR EMAIL:

NOTES:

NOTES:

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



AREA SURVEYED: 7/9 - A-H

Also perimeter A, 9 , 1 & H

SITE CONDITIONS:

WEATHER: Cloudy

TEMPERATURE: 14C

MEMBRANE TEMPERATURE: N/A

RELATIVE HUMIDITY: 63%

TIME: 8.45am - 9.45am

REPORT NUMBER: 005

DATE: 20th April 2017

ACCOMPANIED Stephen Gatehouse

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



OVERVIEW PHOTOS



Overview wall A

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



OVERVIEW PHOTOS



Overview area 7/9 - A-H

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA: 7/9 - A-H also walls A,H 1 , 9

RESTRICTIONS AND LIMITATIONS:

All applications were available for Verification

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA: 7/9 - A-H also walls A,H 1 , 9

RESTRICTIONS AND LIMITATIONS:

No limitations or restrictions

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE

LOCATION/GRID LINE: Wall 1

NOTES:

Application of Hydroprufe 8000 self adhesive on outer wall

, also overlaps on top and continues on inner surface of wall

Photo 2 : outer view of wall 1

Photo 1 : Shows application over the top and then secured on the inner surface



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE



Overview wall A

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report




VERIFICATION ITEM TWO

LOCATION/GRID LINE: 7/8

NOTES: Incorrect use of double sided tape on laps I.e should

GR detailing tape (had run out , more ordered) tried the wrong tape for a small

Section



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed


Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM TWO



Overview , laps outstanding to be taped (ongoing)

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report




VERIFICATION ITEM THREE

LOCATION/GRID LINE: 9/3

NOTES: Pipe penetrations correctly detailed and laps

In this area correctly applied with double sided tape



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM THREE



Edge correctly applied with detailing tape

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



REMEDIATION LOG

Date	Nr	Remediation Description	Y/N
20th Mar	001	No remediation items	✓
20th Mar	001	Protection board still to fix	✓
23rd Mar	002	300mm detailing tape overlaid to edge beams and membrane	✓
23rd Mar	002	Column and edge beam detailing sealed to specification	✓
23rd Mar	002	Pipe penetrations detailed to specification	✓
3rd Apr	003	Columns and edge detailing 5A complete	✓
3rd Apr	003	Repairs in membrane 4A	✓
3rd Apr	003	Outstanding detailing to columns and edge A/B -6/7	✓
10th Apr	004	Wall perimeters primed A, H , 1 & 9	✓
10th Apr	004	Incorrect application of detailing/ remedation tape	✓
10th Apr	004	Correct application of Hydroprufe 8000 on perimeter	✓
20th Apr	005	Wall perimeter membrane correctly installed	✓
20th Apr	005	Incorrect use of double sided tape	
20th Apr	005	Pipe penetrations and edge detailing	✓

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



ADDITIONAL PHOTOS



Application overview



Application on sand blinding



Column detailing



Wall perimeter

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



GAS MEMBRANE TESTING

VISUAL:

YES



NO



SMOKE TEST:

YES



NO



COMPRESSED AIR:

YES



NO



DILECTIC

YES



NO



DESTRUCTIVE:

YES



NO



YES



NO



OTHER:

GRID LINE:

Area: A/H - 1/3+



GRID LINE:

Area A/H 1/4



GRID LINE:

Area A/B-4/7



GRID LINE:

Area A/H - 7/9



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GRID LINE:



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



VERIFICATION SUMMARY

Fifth visit , continuation of perimeter application of Hydroprufe 8000

Also additional slab membrane applied to area 7/9 - A/H

Some minor remediations outstanding but being completed

All installed to BS8485 and verified to CIRIA 735

GEOSHIELD SIGNITURE:

DATE: 20th April 2017

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.