




FIRST FLOOR PLAN

DUE TO AREAS OF EXCESSIVE DAMP AND STAINING IT CAN BE ASSUMED THAT THIS HAS BEEN CAUSED BY WATER INGRESS THROUGH THE ROOF. LEAD HAS BEEN TAKEN FROM OTHER AREAS OF THE BUILDING SO IT WOULD BE SAFE TO ASSUME THAT THE SAME CAN ALSO BE SAID FOR THE MAIN ROOF. THE CONDITION OF THE EXISTING TIMBERS IS AT THIS POINT UNKNOWN AND IT IS LIKELY THAT EXTENSIVE REPAIR AND REPLACEMENT MAY BE REQUIRED.

Date	Scale	Drawn by	Check by
JUNE 2015	1:100@A3	JT	SP
Project No	Drawing No	Revision	
23264	ECS-02	-	

