







Above, the first part of the tyre shop hardstanding being lifted.







Above, the south eastern corner of the site and suspected location of a soakaway.









A drain found below the paint shop which was filled with fragments of roof board.



Above (centre left of picture), the blackened spot location of the Paint Shop 2 sample.





Above, a torch found below the floor of the paint shop.



Above, the XRF analyser testing arisings from hand excavated pit HD1 during the phase 2 investigations.