


RF19

Remove 900mm x 900mm area of previously damaged lath and plaster ceiling finish above level 3 to inspect roof structure above. Trim existing timber joists to form new opening. New loft hatch to be installed to provide permanent access into roof space above. Inspect copper ridge capping to determine source of leak



Legend

 Ceiling finish (typically modern plasterboard) below to be temporarily removed to inspect roof structure / roof voids above

Structural Engineer to inspect all structure to confirm its suitability. Refer to Structural Engineer's information for all structural improvements and alterations.

An asbestos survey must be carried out for all building fabric which is to be disturbed by the temporary removals before the works take place.

