

Appendix 15

Yeomanry House



Plate 1: The photos above show the area of lead theft on the roof and those below the damage to second floor ceiling and floor. Where lath and plaster has been replaced, and joists repaired, these have been exposed due to the damage.



Plate 2: The internal damage is noticeable comparative to the previous images, on the first floor and ground floor due to lead theft on the roof.