


HSEQ Inspection (S2313316)

Today date: 10/09/2026 13:37



General Details

Date Submitted	Inspector	Job Reference	Job ID
10/09/2026 13:35	Dhrupesh Desai	S2313316	N/A
Depot Name	Inspection	Subcontractor	Points
N/A	Tree Cutting Request		1/1
Depot Manager Name	Score Percentage	Inspection Status	Contract
N/A	100%	Acceptable	
Contract Manager	Contract Number		
N/A	N/A		
Location			
20, ST. PETERS HILL, CAVERSHAM,, Reading RG4 7AX, United Kingdom			

Tree Cutting Request Inspection			
	100.00%	1/1	100.00% 3/3
	100.00%	4/4	100.00% 2/2
Total			100.00%

1 Please select which region you are in?

Points: 0

Midlands

2 Please give a detailed summary of the issue and possibly solution.

Points: 0

Tree Cutting Required To Enable Installation To Take Place Or Blue Rope To Be Installed To Enable Installation To Take Place.

3 Is the pole effected by the tree a Joint User Pole?(JUP)

N/A

Points: 0



4 Are there any special requirements or conditions that would need to be considered when carrying out tree cutting?

N/A

Points: 1


5 Please upload a photo of the pole.

Points: 0



6 Please upload a photo of the pole facing the house which should include the tree.

Points: 0



7 Please upload a photo from the house towards the pole. This should include the obstruction.

Points: 0



8 Please upload a photo depicting a suitable position for the bracket on the house.

Points: 0



9 Was the person who owns the tree in at the time of the survey ?

No

Points: 0

10 Surveyor Signature Sign Off.

Points: 0

