



Tree Inventory Report

Reading Borough Council

16 September 2026

Report created by Dan Johnson



Unique ID: 07N6
Parks
Quercus sp.
W3W: solar.salads.towers

Overview Photos



Inventory	
Surveyor	Chris Fitzgerald
Inspection Date	16-Sep-2026
Next Inspection	16-Sep-2027
Trunk Type	Single
Age	Mature
Condition	Poor
Proximity	
Street	BUGS BOTTOM
Area	
Tag	[[Thames-00584]]
Stem Diameter	
Spread	12m
Height	9m
Committee	Parks
Site	Woodland/Copse

Species	
Count	1
Vegetation Type	Broadleaf
Species	Quercus sp.

Maintenance

Requirements	
Date Added	24-Aug-2020
Date Required	24-Aug-2021
Date Completed	22-Dec-2020
Priority	2. Medium
Requirement Type	Partial crown reduce reshape
Requirement Option	
Requirement Info	
Requirement Note	cb canopy inline with conservatory edge (4m from house), reduce height by 2m,

Requirements	
Date Added	24-Aug-2020
Date Required	24-Aug-2021
Date Completed	22-Dec-2020
Priority	2. Medium
Requirement Type	Climbing inspection
Requirement Option	
Requirement Info	
Requirement Note	check decay sound wood in cavities acceptable level, low limb 2m cb from conserv

Requirements	
Date Added	16-Sep-2026
Date Required	16-Oct-2026
Priority	4. Urgent
Requirement Type	Remove crown / Monolith
Requirement Option	
Requirement Info	
Requirement Note	leave as monolith at union at 5m

Considerations	
Consideration	C Stem Bark damage

Considerations	
Consideration	C Stem Included bark / Forked trunk

Considerations	
Consideration	C Stem Decay / Cavity

Considerations	
Consideration	D Crown Decay / Cavity minor

Comment	
Surveyor	Jack Nicholls-Sames
Comment Date	24-Aug-2020
Comment	base garden waste fly tipped otherwise nsvd, twin stemmed at 6m tight fork with fussing small patch of delamination at 4m W with 5mm crack visible, multiple occluding wounds with some decay present, canopy within 1m of property, good vitality

Comment	
Surveyor	Jack Nicholls-Sames
Comment Date	24-Aug-2020
Comment	significant wound to N stem E side possible lightning furrow extends from gl to 9m occluding boring insect present, wound at 2.5m W with some dysfunction swelling - audibly hollowing

Comment	
Surveyor	Chris Fitzgerald
Comment Date	16-Sep-2026
Comment	Large fungal fruiting body (laetiporus sulphureus) seen at approx 5m whilst on Winterberry way. FFB growing on main stem directly below cavity and included union with high likelihood of catastrophic limb failure resulting in significant potential for...

Comment	
Surveyor	Chris Fitzgerald
Comment Date	16-Sep-2026
Comment	large sections of tree to fail into garden or building due to close proximity. Additionally large wound on E side from lightning strike compounding issue.