

Number	Rev	Room	Type	Existing Leaf			Extg Fire Rating	Proposed Fire Rating	Glazing	Architrave		Status	Smoke Seals	Fire Upgrade	Structural Opening		New Doors			Type	Reference	Glazing	Ironmongery	Access Control	Notes
				H	W	Th				Corridor	Room				Height	Width	H	W	Th						
DB 01		Basement	Flush				Unknown					Retained													
DG 01		G01 Lobby	6 Panel glazed	2120	910	47	None	None	3 panes	extg	extg	Modified to suit new levels													Level access required
DG 02		G02 Hall	8 Panel glazed	2170	1020	47	None	None	6 panes	extg	extg	Retained and restored	Y	Y										Yes	
DG 03		G03 Gym	6 Panel timber	2080	850	50	FD30S	FD30S	None	extg	extg	Retained and restored	Y	Y											
DG 04		G04 Gym	6 Panel timber	2080	850	50	None	FD30S	None	extg	extg	Retained and restored	Y	Y											
DG 05		G05 Lounge	6 Panel timber	2080	850	50	None	FD30S	None	extg	extg	Retained and restored	Y	Y											
DG 06		G05 Lounge	Glazed French									Retained and restored													
DG 07		G06 Beverage	6 Panel timber	2060	820	47	None	FD30S	None	extg	extg	Retained and upgraded	Y	Y											
DG 08		G09 Corridor	Modern Flush	2060	850	45	FD30S	FD30S	None	extg	extg	Retained	Y												
DG 09		G08 WC						None		A	B	New			2100	1000	2040	926	44	4 panel	L20/252	None			
DG 10		G10 Stairs	Modern Flush	1920	780	45	FD30S	FD30S	None	extg	extg	Retained	Y												
DG 11		G08 WC	6 Panel timber	2060	810	40	None		None	extg	rem	To be sealed shut													
DG 12		G12 Hallway	Modern Flush	2060	850	45	FD30S	FD30S	None	extg	extg	Retained	Y												
DG 13		G11 Store	Modern Flush	1920	780	45	FD30S	FD30S	None	extg	extg	Retained	Y												
DG 14		G12 Hallway	4 Panel glazed	2070	1060	50	None		2 panes	extg	extg	Retained and restored													
DG 15		G13 WC	4 Panel timber	1950	675	50	None		None	B	B	New			2100	740	2040	660	44	4 panel	L20/252	None			Exisitng door rotten
DG 16		G14 WC	Modern Flush	1970	910	50	None	None	None	B	B	New			2100	810	2040	726	44	4 panel	L20/252	None			Exisitng door rotten
DG 17		G17 Male Change	Modern Flush	2060	820	45	FD30S	None	None	B	B	New			2100	920	2040	826	44	4 panel	L20/252	None			Exisitng door rotten
DG 18		G18 Female						None		B	B	New			2100	900	2040	826	44	4 panel	L20/252	None			
DG 19		G16 Corridor	2 panel timber	unk	unk	unk	None		None	extg	extg	Retained and restored													
DG 20		G21 Store	Timber				None	None	None	extg	extg	Retained and restored													
DG 21		G22										Removed													
DG 22		G20 Store										New			2370	780	2330	700		Ledged Braced	L20/271	None			No door currently
DF 01		F01 Stairs	Modern Flush	1980	860	45	FD30S			C	C	Possibly omitted													
DF 02		F03 TV Room					None	FD30S		C	C	Missing	Y	Y			1990	860	44	4 panel	L20/253	None			Exisitng door rotten
DF 03		F04 Yoga	4 Panel timber	1980	860	35	None	FD30S		extg	extg	Retained and restored	Y	Y											
DF 04		F05 Store	4 Panel timber	1980	860	35	None	FD30S		extg	extg	Retained and restored	Y	Y											
DF 05		F06 Counselling	4 Panel timber	1980	860	35	None	FD30S		extg	extg	Retained and restored	Y	Y											
DF 06		F05 Store	4 Panel timber	1980	670	35	None			extg	extg	Retained and restored													
DF 07		F08 Quiet Room	Modern Flush	1980	830	45	FD30S	FD30S				Retained and restored	Y												
DF 08		F09 Store	Modern Flush				None					Retained													
DF 09		F11 Office	4 Panel timber	1950	850	35	None	FD30S		extg	extg	Retained and restored	Y	Y											
DF 10		F17 Stair	Modern Flush	1960	770	45	FD30S	FD30S		extg	extg	Retained	Y												
DF 11		F12 Quiet Room	4 Panel timber	1960	820	35	None	FD30S		extg	extg	Replaced	Y				1990	860	44	4 panel	L20/253	None			Exisitng door rotten
DF 12		F13 Store	Modern Flush	1950	630	45	FD30S	FD30S		extg	extg	Retained	Y												
DF 13		F16 WC	4 Panel timber	1960	770	45	None			extg	extg	Retained and restored													
DF 14		F15 WC	4 Panel timber	1960	770	45	None			extg	extg	Retained and restored													
DF 15		F18 Plant	Modern Flush	1960	820	45	FD30S	FD30S		B	B	Retained	Y	Y											
DF 16		F19 Activity	Modern Flush	1960	820	45	FD30S	FD30S		B	B	Retained	Y	Y											
DF 17		F11 Office	4 Panel timber	1960	810	35	None			extg	extg	Retained													

Note: Structural openings for replacement doors to be checked on site prior to manufacture