



RISK ASSESSMENT

Company Name:	Cawarden Co Ltd.	Date: 11/11/2019	Start: TBC	Assessment No:	01
Assessor: William Crooks		Task: Removal of Cement Sheets			

Haz No.	Significant Hazards Look only for hazards which you could reasonably expect to result in significant harm e.g. slips/trips, work at height, falling objects, vehicles, electricity etc. (STEP 1)	People Affected List groups of people who may be at risk e.g. maintenance staff, contractors, cleaners, public etc. (STEP 2)	Control measures List controls that are already in place to control the risk e.g. physical safeguards, training, personal protective equipment etc. (STEP 3)	Level of Risk Decide on the level of risk remaining. (Likelihood x Severity)			Further Action Required List further action required to control significant risks. If there are lots to do, make an action list. (STEP 4)
				High	Med	Low	
01	Broken and degraded asbestos. Releasing fibers causing serious respiratory problems.	Operatives	Training in removal of notifiable-non-licensed asbestos. Light spray of water FFP3 mask T5 Gloves			x	Site supervisor to fill out exposure form and return to Safety Manager on completion of work.
02	Manual Handling of asbestos and bags causing injury to back, cuts to fingers and fractures to feet and toes.	Operatives	Manual handling training Manual handling risk assessment Gloves Safety Foot wear			x	Site supervisor to monitor operatives when carrying out manual handling tasks

Haz No.	Significant Hazards Look only for hazards which you could reasonably expect to result in significant harm e.g. slips/trips, work at height, falling objects, vehicles, electricity etc. (STEP 1)	People Affected List groups of people who may be at risk e.g. maintenance staff, contractors, cleaners, public etc. (STEP 2)	Existing Controls List controls that are already in place to control the risk e.g. physical safeguards, training, personal protective equipment etc. (STEP 3)	Level of Risk Decide on the level of risk remaining. (Likelihood x Severity)			Further Action Required List further action required to control significant risks. If there are lots to do, make an action list. (STEP 4)
				High	Med	Low	
03	Dust arising from removal of fill causing serious respiratory problems.	Operatives Machine driver Surrounding site operatives	Light spray of water if required FFP3 dust mask			x	
04	Noise arising from use of plant and machinery causing chronic and acute ear problems.	Operatives Machine driver Surrounding site operatives	Ear defenders			x	
05	Slips trips and falls causing serious injury, cuts and fractures.	Operatives	Good house keeping Safety footwear			x	Site supervisor to check work area
06	Movement of vehicles on site coming into contact with persons causing serious injury or even fatality.	Operatives Surrounding site Operatives	plan. Banks man High visibility vests			x	
07	Pre-existing damage to plant deteriorating further resulting in injuries to nearby persons	Operatives Machine drivers	12 monthly checks Servicing Pre-start checks			x	Site supervisor to check operator as carried out all checks prior to works.