



- ### HEALTH & SAFETY INFORMATION
- To be read in conjunction with Viewpoint's Designer Hazard Identification Checklist - Risk Assessment for existing or proposed service positions seen on drawings. In addition to the following, the contractor must also be aware of the following information:
- The following risks should be noted:
- 1 Highway adjacent to the site:
 - Is: Hoarding required to protect pedestrians & vehicles within the highway.
 - Overseeing of plant & machinery is strictly prohibited without the prior agreement of the local authority.
 - 2 Existing services within the site:
 - Is: In areas to be excavated, the contractor is to locate services prior to construction, by hand digging.
 - 3 Existing services adjacent to site:
 - Is: In areas to be excavated, the contractor is to locate services prior to construction, by hand digging.

viewpoint
associates llp

landscape, environmental & horticultural consultants

Web: www.view-point.co.uk
E-mail: info@view-point.co.uk

Layout showing proposed soft landscaping general arrangements

Drawing No. 1610a-01	Revision. C
--------------------------------	-----------------------