






No temporary opening up works are required to provide further access within RF12 for the necessary investigations to be undertaken.

Structural Engineer to inspect all structure to confirm its suitability. Refer to Structural Engineer's information for all structural improvements and alterations.

An asbestos survey must be carried out for all building fabric which is to be disturbed by the temporary removals before the works take place.

01 ROOF RF12 - TEMPORARY ACCESS AND INVESTIGATIONS

Scale Bar. 1:50



00/29.09.25 Issued for Planning
revision/date note



project

Reading Town Hall,
Alterations & Improvements

title

Roof RF12 Temporary
Access And Investigations

scale

1:50 @A3

status

PLANNING

job no.

997

dwg no.

262

status/revision

PL00

© Morse Webb Ltd