

Roof repair and maintenance work for 8&10 Church Street, RG4 8DZ (10) / RG4 8AT (8)



The existing roof profile will remain unchanged by the roofing works. It's appearance will look the same as current, except cleaned.

- Scaffolding to be erected.
- The existing plain clay tiles, underlay membrane and battens to be removed and cleaned ready for reuse.
- The timbers to be cleaned and inspected.

Should any existing clay tiles, underlay membrane or battens be incapable of reuse, source and fit appropriate / like-for-like material to use - so similar plain clay tiles that match the existing in colour and appearance - also the underlay membrane must be breathable.

Glenn & Chris Rothwell own no. 6 Church Street next door. Work has recently been completed on the roof for no. 6 Church Street by Dunne Historical Building Restoration. <https://www.dunne.ltd/>

When the scaffolding for no. 6 was erected, we could see that repair work was needed to the front aspect of the roof of no. 8&10 as well as at least two points on the rear roof.

Glenn & Chris are aware that repair work is needed and supportive of this being done, as we were the work they have just had done.

We have been impressed by the expertise and standard of work completed by Dunne & Co and so intend to ask them to do the roof repair work needed.



