



Plate 31 – Part north elevation of the L shape building



Plate 32 – Door opening inserted to the north elevation of the L shape building



Plate 33 – Timber purlin foot and bargeboard detail to the verges of the north elevation of the L shape building



Plate 34 – View southwest through the ground floor into the main building



Plate 35 – Interior view of the south elevation of the main building



Plate 36 – View east through the ground floor of the main building into the later additions to the east




Plate 37 – Modern bar fitting inserted against the interior of the north elevation of the main building



Plate 38 – View towards the northwest corner of the interior of the ground floor




Plate 39 – Back fitting of the bar servery



Plate 40 – Renewed fireplace within original location with chimney breast to the west elevation of the L shape building



Plate 41 – Interior view of the ground floor of the L shape building with section of original west elevation retained to the right of the image



Plate 42 – Door opening (to kitchen) within a modern partition inserted to the ground floor of the L shape building



Plate 43 – View from within the ground floor of the L shape building into a later addition to the west



Plate 44 – View south into the interior of the pyramidal addition, wall to the right is the original east elevation of the L shape building



Plate 45 – View east through the ground floor of the later additions towards the pyramidal addition



Plate 46 – Interior of the later porch addition on the south elevation



Plate 47 – Interior window detail to the windows within the pyramidal addition to the east



Plate 48 – Interior window detail to the later porch addition



Plate 49 – Ovolo moulded glazing bars typical to the ground floor windows of the south elevation of the main building



Plate 50 – Interior view of the south elevation



Plate 51 – Interior view of the south elevation of the west addition to the main building



Plate 52 – Interior of the west addition



Plate 53 – View south through the ground floor of the west addition



Plate 54 – View east through the ground floor of the west addition



Plate 55 – View north through the ground floor



Plate 56 - Door opening to the male WCs located within the mid-20th century addition to the north of the main building



Plate 57 – View northeast towards the original west external elevation of the L shape building



Plate 58 – Timber panel door to the cellar area



Plate 59 – Cellar steps



Plate 60 – Cellar area located below part of the ground floor of the mid-20th century addition to the north




Plate 61 – Cellar steps



Plate 62 – Rear corridor through the mid-290th century addition to the north




Plate 63 – View west through the ground floor of the main building towards a remaining section of the west elevation



Plate 64 – Metal framed top light window to the glazed screen between the office and staircase



Plate 65 – Remains of glazed screen frame between the office and the staircase




Plate 66 – Staircase to first floor level




Plate 67 – Staircase detail



Plate 68 – staircase detail



Plate 69 – Staircase to the first floor



Plate 70 – First floor landing area of the main building with splayed entrance to the south rooms



Plate 71 – Surround detail to the opening to the south rooms from the first-floor landing of the main building



Plate 72 – Architrave detail to the surround to the opening to the south rooms



Plate 73 – First floor room to the southwest of the main building with off centre chimney breast



Plate 74 – Later opening inserted within original partition wall between the southwest and southeast first floor rooms of the main building



Plate 75 – Interior view of the first-floor window to the west of the south elevation of the main building



Plate 76 – Skirting board detail to the southwest first floor room of the main building



Plate 77 – Original lath and plasterwork to the first-floor ceiling of the main building



Plate 78 – Fire surround to the east wall of the southeast first floor room of the main building



Plate 79– Fire surround to the east wall of the southeast first floor room of the main building




Plate 80 – Later partition wall inserted to the north of the southeast first floor room



Plate 81 – Interior view of the eastern first floor window to the south elevation



Plate 82 – Interior of the northwest first floor room of the main building



Plate 83 – Fire surround to the west floor of the northwest first floor room of the main building




Plate 84 – Cupboard area within the northeast corner of the northwest first floor room




Plate 85 – Typical modern fire door present to the first-floor accommodation




Plate 86 – View east along the access corridor to the L shape building; step to centre of the image depicts the original extent of the east wall of the main building



Plate 87 – Interior view of later first floor window within the north elevation of the two-storey addition to the west



Plate 88 – Cupboards located to the south of the first-floor access corridor between the main building and the L shape building



Plate 89 – Interior of the south first floor room of the L shape building looking southwest with chimney breast to the right of the image



Plate 90 - Interior of the south first floor room of the L shape building looking northeast



Plate 91 - Interior of the south first floor room of the L shape building looking north



Plate 92 – Kitchen area within the shirt arm of the L shape building



Plate 93 - Interior of the north first floor room of the L shape building looking northeast



Plate 94 – View through the north first floor room of the L shape building towards the bathroom which is accommodated within the short, east projecting arm of the building



Plate 95 - Interior of the north first floor room of the L shape building looking west



Plate 96 – View northeast across the carparking area within the Site



Plate 97 – View north across the western extent of the carpark



Plate 98 – View northwest across the western extent of the carpark



Plate 99 – View west across the western extent of the carpark



Plate 100 – Interior view of the original garage addition