



Rev.	Date	Note	Author	Checked
-	dd/mm/yy	Note	XXX	XXX


EXISTING DILAPIDATED BASEMENT EXTERNAL STEPS
(To be removed)



ELEVATION **A** 1/20





SECTION 1/20



PLAN 1/50

- MATERIAL KEY**
- ① Natural stone slab stair tread
 - ② Cast iron riser with decorative circular pattern and frame



DETAIL SECTION 1/5



Figure 01



Figure 02



Figure 03

Project	Refurbishment & Alterations Carlisle House Reading RG1 7NG					Drawing	Drawing & Photographic Recording: Existing Basement External Steps			
						Job-Dwg Number	18009-PL-35		Rev.	-
Client	Turner Property Ltd					WESTON + CO ARCHITECTS Watlington House 44 Watlington Street Reading, RG1 4RJ T. 0118 375 0252 www.weston-co.com				
Status	Planning									
Scale	1/5, 1/20 & 1/50		Sheet Size A3							
Author	IG	Checked	CTW	Date	17/04/2023					