



Noise measurement report

Date: 05/07/2022, 11:13 am

Operator: Jack Eddy

Place: 1st Floor Middle Point of Floor

Measurement results

Measurement time (hh:mm:ss)	00:04:09
LAeq	40.3 dB
Max. level	64.8 dB
LCpeak	80.2 dB
TWA	18.7 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed in the middle of the floor as per the position show on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.



Noise measurement report

Date: 05/07/2022, 10:58 am

Operator: Jack Eddy

Place: 1st Floor (West) Elevation

Measurement results

Measurement time (hh:mm:ss)	00:00:12
LAeq	43.5 dB
Max. level	58.8 dB
LCpeak	78.0 dB
TWA	7.7 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed on the window sill in position show on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.



Noise measurement report

Date: 05/07/2022, 10:57 am

Operator: Jack Eddy

Place: 2nd Floor (North) Elevation

Measurement results

Measurement time (hh:mm:ss)	00:00:17
LAeq	43.8 dB
Max. level	70.8 dB
LCpeak	74.1 dB
TWA	19.0 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed on the window sill in position show on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.