



Noise measurement report

Date: 05/07/2022, 11:07 am

Operator: Jack Eddy

Place: 2nd Floor Middle Point of Floor

Measurement results

Measurement time (hh:mm:ss)	00:04:57
LAeq	38.2 dB
Max. level	69.7 dB
LCpeak	75.5 dB
TWA	33.6 dB
Dose	0.0 %
Projected dose	0.1 %

Notes

Placed in the middle of the floor as per the position shown on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.



Noise measurement report

Date: 05/07/2022, 11:00 am

Operator: Jack Eddy

Place: 2nd Floor (North) Elevation

Measurement results

Measurement time (hh:mm:ss)	00:00:18
LAeq	39.0 dB
Max. level	55.6 dB
LCpeak	72.8 dB
TWA	4.4 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed on the window sill in position show on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.



Noise measurement report

Date: 05/07/2022, 10:59 am

Operator: Jack Eddy

Place: 2nd Floor (West) Elevation

Measurement results

Measurement time (hh:mm:ss)	00:00:19
LAeq	38.4 dB
Max. level	53.3 dB
LCpeak	67.4 dB
TWA	4.3 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed on the window sill in position show on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.