



Noise measurement report

Date: 05/07/2022, 10:47 am

Operator: Jack Eddy

Place: 3rd Floor Middle Point of Floor

Measurement results

Measurement time (hh:mm:ss)	00:00:24
LAeq	34.3 dB
Max. level	49.1 dB
LCpeak	69.8 dB
TWA	5.8 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed in the middle of the floor as per the position shown on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.



Noise measurement report

Date: 05/07/2022, 10:46 am

Operator: Jack Eddy

Place: 3rd Floor (West) Elevation

Measurement results

Measurement time (hh:mm:ss)	00:00:29
LAeq	36.5 dB
Max. level	52.9 dB
LCpeak	70.4 dB
TWA	3.3 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed on the window sill in position show on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.



Noise measurement report

Date: 05/07/2022, 10:50 am

Operator: Jack Eddy

Place: 3rd Floor (North) Elevation

Measurement results

Measurement time (hh:mm:ss)	00:00:24
LAeq	38.4 dB
Max. level	53.3 dB
LCpeak	71.1 dB
TWA	9.9 dB
Dose	0.0 %
Projected dose	0.0 %

Notes

Placed on the window sill in position show on floor plans prepared by JE Architecture LTD.

Overcast day with heavy traffic and roadworks.