


LEVEL MONITORING - RELATIVE SURVEY READINGS

Provider Details		Client Details	
Name:	MHN Ltd	Insurance Co.:	
		Client Name:	
Date of Issue:	20/12/21	Contact:	
		Email:	
		Client Ref:	
Monitoring Details		Address:	
Instruction Date:	8/1/21	Address:	
First Reading Date:	21/01/2021	Address:	
Maximum No Visits:	10	Town:	
Anticipated Expiry Date:	Feb 2022	County:	
Monitoring Int:	6 Weekly	Post Code:	

Target Date:														
Reading Date:				21/1/21	8/3/21	24/4/21	9/6/21	28/7/21	24/9/21	3/11/21	17/12/21			
Issue Date:				25/1/21	10/3/21	26/4/21	10/6/21	29/7/21	27/9/21	4/11/21	20/12/21			
Row No.	Point Name	X Co-ordinate	Y Co-ordinate	1	2	3	4	5	6	7	8	9	10	11
1		0.00	0.00											
2	1	2.30	0.00	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000			
3		3.50	0.00											
4		3.50	3.00											
5	2	5.50	3.00	10.0903	10.0900	10.0905	10.0901	10.0904	10.0911	10.0909	10.0903			
6	3	13.50	3.00	10.0934	10.0929	10.0941	10.0938	10.0945	10.0947	10.0944	10.0944			
7	4	24.00	3.00	10.0144	10.0136	10.0140	10.0143	10.0150	10.0151	10.0154	10.0148			
8	5	24.00	-1.00	10.0252	10.0251	10.0263	10.0261	10.0263	10.0268	10.0272	10.0271			
9	6	24.00	-7.00	10.0991	10.0981	10.0975	10.0989	10.0988	10.0969	10.0983	10.0983			
10	7	17.00	-7.00	10.0927	10.0929	10.0925	10.0937	10.0937	10.0939	10.0942	10.0938			
11	8	17.00	-7.50	10.0849	10.0852	10.0851	10.0851	10.0856	10.0853	10.0856	10.0858			
12		16.00	-7.50											
13		15.50	-8.00											
14		13.50	-8.00											
15		13.00	-7.50											
16	9	12.00	-7.50	10.0830	10.0827	10.0831	10.0831	10.0837	10.0843	10.0840	10.0831			
17		12.00	-7.00											
18	10	11.50	-7.00	10.0919	10.0918	10.0917	10.0919	10.0935	10.0943	10.0941	10.0942			
19	11	3.50	-7.00	10.0847	10.0856	10.0860	10.0862	10.0865	10.0860	10.0862	10.0861			
20		3.50	-6.00											
21		0.00	-6.00											
22														
23														
24														
25														
26														
27														
28														
29														
30														
31														
32														




- 20/12/2021
The occupier raised no new concerns.
- It was not possible to install all stations within a common brickcourse. The initial readings cannot be interpreted as Distortion Data.
- Readings have been made relative to station 1 as requested. It has an elevation value of 10.0000m. If this is not acceptable please advise if a deep datum is required.
- Printed on 06/01/2022
- Further readings to be taken in January 2022.

LEVEL MONITORING - RELATIVE MOVEMENT SKETCH

Client: Sedgwick

Client Ref: ###




Reading 1 (21/1/21) Reading 2 (8/3/21) Reading 3 (24/4/21) Reading 4 (9/6/21) Reading 5 (28/7/21) Reading 6 (24/9/21)
 Reading 7 (3/11/21) Reading 8 (17/12/21) Reading 9 (0/1/00) Reading 10 (0/1/00) Reading 11 (0/1/00) Reading 12 (0/1/00)

Notes:


Vertical distorted scale 1: 5

Point labels give level difference of last reading from original datum in mm.


1



2



3



Standard Comments for selection in Readings and Sketch Worksheets
User may edit these as appropriate

Standard Comments	
No Comment	
Standard Comment 1	The Occupier expressed concerns
Standard Comment 2	The Occupier expressed no new concerns
Standard Comment 3	Standard Comment 3
Standard Comment 4	Standard Comment 4
Standard Comment 5	

Standard Bullet
●