

Project:
Refurbishment & Alterations

Site Address:
Carlisle House
118 Oxford Road
Reading
RG1 7NG

Client:
Turner Property Ltd

Document Title:
Photographic Survey

Document Ref:
18009.9.1_22.03.25_PS

Author:
IG

Checked:
CW

WESTON + CO ARCHITECTS

Watlington House,
44 Watlington Street,
Reading,
RG1 4RJ


0118 375 0252

studio@weston-co.com

CONTENTS

1.0	SITE EXTERIOR
2.0	SITE INTERIOR
3.0	BASEMENT
4.0	FLAT NO.1
5.0	FLAT NO.2
6.0	FLAT NO.3
7.0	FLAT NO.4
8.0	INTERIOR COMMUNAL AREAS - GROUND FLOOR
9.0	INTERIOR COMMUNAL AREAS - FIRST FLOOR
10.0	LOFT
11.0	ROOF
12.0	SOUTH ELEVATION
13.0	EAST ELEVATION
14.0	NORTH ELEVATION
15.0	WEST ELEVATION

1.0 - SITE EXTERIOR



Key plan


Photograph 1



Photograph 2


Photograph 3


Photograph 4


Photograph 5

1.0 - SITE EXTERIOR



Key plan



Photograph 6




Photograph 7



Photograph 8

2.0 - SITE INTERIOR



Key plan



Photograph 9



Photograph 10



Photograph 11




Photograph 12



Photograph 13

2.0 - SITE INTERIOR



Key plan


Photograph 14


Photograph 15



Photograph 16


Photograph 17


Photograph 18


Photograph 19

2.0 - SITE INTERIOR



Key plan



Photograph 20




Photograph 21



Photograph 22



Photograph 23




Key plan


Photograph 24


Photograph 25


Photograph 26


Photograph 27




Key plan


Photograph 28


Photograph 29


Photograph 30




Key plan


Photograph 31


Photograph 32


Photograph 33



Key plan



Photograph 34



Photograph 35




Photograph 36



Photograph 37



Photograph 38




Key plan



Photograph 39



Photograph 40



Key plan



Photograph 41




Photograph 42



Photograph 43



Photograph 44



Key plan



Photograph 45




Photograph 46



Photograph 47



Photograph 48



Key plan




Photograph 49



Photograph 50



Photograph 51



Key plan




Photograph 52



Photograph 53



Photograph 54




Key plan



Photograph 55



Photograph 56



Key plan



Photograph 57




Photograph 58



Photograph 59



Photograph 60



Key plan



Photograph 61




Photograph 62



Photograph 63

4.0 - FLAT NO.1



Key plan



Photograph 64



Photograph 65



Photograph 66




Photograph 67



Photograph 68


4.0 - FLAT NO.1



Key plan



Photograph 69



Photograph 70




Photograph 71



Photograph 72



Photograph 73




Key plan


Photograph 74


Photograph 75


Photograph 76


5.0 - FLAT NO.2



Key plan



Photograph 77


Photograph 78


Photograph 79


Photograph 80

5.0 - FLAT NO.2



Key plan


Photograph 81


Photograph 82



Photograph 83


Photograph 84


Photograph 85



Photograph 86

5.0 - FLAT NO.2



Key plan



Photograph 87


Photograph 88


Photograph 89


Photograph 90

5.0 - FLAT NO.2




Key plan


Photograph 91


Photograph 92



Photograph 93


6.0 - FLAT NO.3



Key plan


Photograph 94


Photograph 95



Photograph 96


Photograph 97


Photograph 98


Photograph 99

6.0 - FLAT NO.3



Key plan



Photograph 100




Photograph 101




Photograph 102

6.0 - FLAT NO.3



Key plan


Photograph 103



Photograph 104


Photograph 105


Photograph 106


Photograph 107

6.0 - FLAT NO.3




Key plan



Photograph 108


Photograph 109



Photograph 110



Photograph 111

6.0 FLAT - NO.3




Key plan



Photograph 112


Photograph 113


Photograph 114


Photograph 115


Photograph 116



Key plan



Photograph 117




Photograph 118




Photograph 119



Photograph 120



Key plan



Photograph 121



Photograph 122




Photograph 123




Photograph 124

7.0 - FLAT NO.4



Key plan


Photograph 125


Photograph 126



Photograph 127


Photograph 128


Photograph 129


Photograph 130

7.0 - FLAT NO.4



Key plan



Photograph 131


Photograph 132


Photograph 133


Photograph 134

7.0 - FLAT NO.4




Key plan


Photograph 135


Photograph 136


Photograph 137

7.0 - FLAT NO.4




Key plan


Photograph 138


Photograph 139


Photograph 140


7.0 - FLAT NO.4




Key plan



Photograph 141


Photograph 142



Key plan



Photograph 143


Photograph 144



Photograph 145


Photograph 146


Photograph 147




Key plan



Photograph 148



Photograph 149


Photograph 150


Photograph 151


Photograph 152


Photograph 153




Key plan



Photograph 154




Photograph 155



Photograph 156



Photograph 157



Key plan



Photograph 158



Photograph 159



Photograph 160



Photograph 161



Photograph 162

12.0 - SOUTH ELEVATION



Photograph 163



Photograph 164



Photograph 165



Photograph 166



Photograph 167

13.0 EAST - ELEVATION



Photograph 168



Photograph 169



Photograph 170



Photograph 171



Photograph 172



Photograph 173



Photograph 174



Photograph 175

13.0 - EAST ELEVATION



Photograph 176



Photograph 177



Photograph 178



Photograph 179

14.0 - NORTH ELEVATION



Photograph 180



Photograph 181



Photograph 182



Photograph 183



Photograph 184



Photograph 185

15.0 - WEST ELEVATION



Photograph 186



Photograph 187



Photograph 188



Photograph 189



Photograph 190