



PHOTOGRAPH – VIEWPOINT 24 (WINTER 2019/2020) VALUE: HIGH
VIEW LOOKING EAST TOWARDS THE SITE FROM CYCLE ROUTE NO. 5. VIEWS OF THE SITE ARE TRUNCATED BY THE INTERVENING VEGETATION.



PHOTOGRAPH – VIEWPOINT 24 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 26 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING SOUTH-WEST TOWARDS THE SITE FROM THE PUBLIC RIGHTS OF WAY 266/26/10 ADJACENT TO ROSEHILL RIDING STABLES. VIEWS OF THE SITE ARE OBSCURED BY THE INTERVENING VEGETATION.



PHOTOGRAPH – VIEWPOINT 26 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 25 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING EAST TOWARDS THE SITE FROM THE WESTERN BRIDLEWAY. THE WATER TOWER AND DWELLINGS SET AMONGST TREES ARE APPARENT. HOWEVER, THE VIEWS OF THE SITE ARE TRUNCATED BY THE INTERVENING VEGETATION.



PHOTOGRAPH – VIEWPOINT 25 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 25 (WINTER 2019/2020)

CUT LINE





PHOTOGRAPH – VIEWPOINT 25 (SUMMER 2021)





PHOTOGRAPH – VIEWPOINT 27 (WINTER 2019/2020)

VALUE: LOW

VIEW LOOKING EAST FROM THE EDGE OF GRAVEL HILL AT HIGHDOWN AVENUE. VIEWS OF THE SITE ARE OBSCURED BY THE ORIENTATION OF THE DWELLINGS. HOWEVER THE TREE CANOPIES ARE EVIDENT BETWEEN AND ABOVE THE DWELLINGS.



PHOTOGRAPH – VIEWPOINT 27 (SUMMER 2021)




FIGURE 18 – LOCATION PLAN SHOWING VISUAL SUMMARY FROM DISTANT AREA (FABRIK, 2019)



PHOTOGRAPH – VIEWPOINT 28 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING SOUTH FROM THE NORTHERN PORTION OF KIDMORE END ROAD. VIEWS OF THE SITE ARE WHOLLY TRUNCATED BY THE INTERVENING TOPOGRAPHY AND THE LAYERS OF VEGETATION.



PHOTOGRAPH – VIEWPOINT 28 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 29 (WINTER 2019/2020) **VALUE: HIGH**
VIEW LOOKING SOUTH FROM CHALKHOUSE GREEN ROAD ON THE EDGE OF CHILTERNS AONB. VIEWS OF THE SITE ARE WHOLLY TRUNCATED BY THE EXISTING DWELLINGS AND LAYERS OF VEGETATION.



PHOTOGRAPH – VIEWPOINT 29 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 29 (WINTER 2019/2020)

CUT LINE





PHOTOGRAPH – VIEWPOINT 29 (SUMMER 2021)

CUT LINE



CUT LINE

CUT LINE





PHOTOGRAPH – VIEWPOINT 30 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING SOUTH-WEST FROM PUBLIC FOOTPATH 266/14/10. VIEWS OF THE SITE ARE WHOLLY TRUNCATED BY THE INTERVENING LAYERS OF VEGETATION.



PHOTOGRAPH – VIEWPOINT 30 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 30 (WINTER 2019/2020)

CUT LINE





PHOTOGRAPH – VIEWPOINT 29 (SUMMER 2021)

CUT LINE



CUT LINE

CUT LINE





PHOTOGRAPH – VIEWPOINT 31 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING EAST TOWARDS THE SITE AT THE HIGH POINT IN GRAVEL HILL. VIEWS OF THE SITE ARE TRUNCATED BY VEGETATION AND THE BUILT FORM IN THE FOREGROUND.



PHOTOGRAPH – VIEWPOINT 31 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 31 (WINTER 2019/2020)

CUT LINE