



PHOTOGRAPH – VIEWPOINT 5 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING WEST AT KIDMORE END ROAD LOOKING TOWARD THE MAIN SITE ENTRANCE. OPEN VIEWS OF THE CLUB HOUSE AND THE BOUNDARY VEGETATION, TOGETHER WITH TREES WITHIN THE SITE OCCUR FROM THE RESIDENTIAL AND TRANSIENT RECEPTORS.



PHOTOGRAPH – VIEWPOINT 5 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 5 (WINTER 2019/2020)

CUT LINE





CUTLINE

PHOTOGRAPH – VIEWPOINT 5 (SUMMER 2021)



CUTLINE

CUTLINE



PHOTOGRAPH – VIEWPOINT 5A (WINTER 2019/2020)

VALUE: LOW

VIEW LOOKING WEST AT KIDMORE END ROAD NEAR THE REAR SITE GATE. OPEN VIEWS OF THE SITE ENTRANCE AND THE BOUNDARY VEGETATION TOGETHER WITH THE TREES WITHIN THE SITE OCCUR FROM THE RESIDENTIAL AND TRANSIENT RECEPTORS, AND IN THE CONTEXT OF THE NEIGHBOURING DWELLINGS AND RESIDENTIAL STREET SCENE.



PHOTOGRAPH – VIEWPOINT 5A (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 5A (WINTER 2019/2020)

CUT LINE



CUT LINE

CUT LINE




PHOTOGRAPH – VIEWPOINT 5A (SUMMER 2021)



THIS PAGE IS LEFT BLANK INTENTIONALLY



PHOTOGRAPH – VIEWPOINT 6 (WINTER 2019/2020) **VALUE: LOW**
VIEW LOOKING SOUTH-EAST AT KIDMORE END ROAD / TWIN OAKS JUNCTION. OPEN VIEWS OF THE HEDGEROW BOUNDARY AND MATURE TREES IN THE EASTERN PART OF THE SITE OCCUR WITH THE INTERVENING RESIDENTIAL BUILT FORM RESTRICTING WIDER VIEWS OF THE SITE.



PHOTOGRAPH – VIEWPOINT 6 (SUMMER 2021)



CUT LINE

PHOTOGRAPH – VIEWPOINT 6 (WINTER 2019)



CUT LINE



PHOTOGRAPH – VIEWPOINT 6 (SUMMER 2021)





PHOTOGRAPH – VIEWPOINT 7 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING WEST FROM BROOKLYN DRIVE. VIEWS OF THE SITE ARE TRUNCATED BY THE LAYERS OF VEGETATION. THE SITE OR IT'S INTERNAL VEGETATION ARE THEREFORE NOT READILY DISCERNED.



PHOTOGRAPH – VIEWPOINT 7 (SUMMER 2021)

THIS PAGE IS LEFT BLANK INTENTIONALLY



PHOTOGRAPH – VIEWPOINT 7 (WINTER 2019/2020)

CUT LINE



CUT LINE



PHOTOGRAPH – VIEWPOINT 7 (WINTER 2019)

CUT LINE



CUT LINE



PHOTOGRAPH – VIEWPOINT 8 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING WEST FROM THE ROUNDABOUT AT BROOKLYN DRIVE. VIEWS OF THE SITE ARE PREDOMINANTLY OBSCURED DUE TO THE INTERVENING DWELLINGS, HOWEVER TREE CANOPIES WITHIN THE SITE ARE APPARENT ABOVE THE DWELLINGS.



PHOTOGRAPH – VIEWPOINT 8 (SUMMER 2021)

THIS PAGE IS LEFT BLANK INTENTIONALLY




PHOTOGRAPH – VIEWPOINT 8 (WINTER 2019/2020)

CUT LINE



CUT LINE

CUT LINE



PHOTOGRAPH – VIEWPOINT 8 (SUMMER 2021)





PHOTOGRAPH – VIEWPOINT 9 (WINTER 2019/2020) **VALUE: LOW**
VIEW LOOKING WEST FROM THE NORTHERN PART OF BROOKLYN DRIVE. VIEWS OF THE SITE ARE TRUNCATED BY THE LAYERS OF VEGETATION AND THE VEGETATION WITHIN THE SITE IS NOT READILY DISCERNED.



PHOTOGRAPH – VIEWPOINT 9 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 9 (WINTER 2019/2020)

CUT LINE



CUT LINE



CUT LINE



CUT LINE



PHOTOGRAPH – VIEWPOINT 10 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING WEST FROM BROOKLYN DRIVE ROUNDABOUT. THE SITE VEGETATION WITHIN THE SITE IS APPARENT IN BETWEEN OF DWELLINGS. THE WIDER VIEWS OF THE SITE ARE LIMITED BY THE INTERVENING BUILT FORM.

THIS PAGE IS LEFT BLANK INTENTIONALLY



PHOTOGRAPH – VIEWPOINT 10 (SUMMER 2021)



CUT LINE

PHOTOGRAPH – VIEWPOINT 10 (WINTER 2019/2020)



CUT LINE

CUT LINE



PHOTOGRAPH – VIEWPOINT 10 (SUMMER 2021)





PHOTOGRAPH – VIEWPOINT 11 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING SOUTH-WEST IN THE EDGE OF SETTLEMENT AT KIDMORE END ROAD. VIEWS OF THE SITE ARE TRUNCATED BY THE LAYERS OF VEGETATION AND THE UNDULATING LANDFORM OF THE NORTHERN PART OF THE GOLF COURSE.



PHOTOGRAPH – VIEWPOINT 11 (SUMMER 2021)

THIS PAGE IS LEFT BLANK INTENTIONALLY



CUT LINE

PHOTOGRAPH – VIEWPOINT 11 (WINTER 2019/2020)



CUT LINE



CUT LINE

PHOTOGRAPH – VIEWPOINT 11 (SUMMER 2021)



CUT LINE



PHOTOGRAPH – VIEWPOINT 12 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING NORTH FROM THE EMMER GREEN PLAY FIELDS. VIEWS OF THE VEGETATION WITHIN THE SITE OCCUR BETWEEN AND OVER THE DWELLINGS.



PHOTOGRAPH – VIEWPOINT 12 (SUMMER 2021)

THIS PAGE IS LEFT BLANK INTENTIONALLY



CUT LINE

PHOTOGRAPH – VIEWPOINT 12 (WINTER 2019/2020)



CUT LINE

CUT LINE



PHOTOGRAPH – VIEWPOINT 12 (SUMMER 2021)





PHOTOGRAPH – VIEWPOINT 13 (WINTER 2019/2020) VALUE: LOW
VIEW LOOKING NORTH FROM THE GROVE ROAD ALLOTMENTS. VIEWS OF THE SITE ARE TRUNCATED BY THE LAYERS OF VEGETATION AND EMMER GREEN PRIMARY SCHOOL BEYOND.



PHOTOGRAPH – VIEWPOINT 13 (SUMMER 2021)



PHOTOGRAPH – VIEWPOINT 13 (WINTER 2019/2020)

CUT LINE





PHOTOGRAPH – VIEWPOINT 13 (SUMMER 2021)



CUT LINE

CUT LINE

