

tree condiotion arb impact assessment
Key
trees condition u
trees condition c
trees condition B
root protection area
root protection fence
T1
T2
T3
T4
T5
T6
T7
T8
T9
T10
T11
Classroom construction
The Wren School eco Classrom development
15/1/2022 draeing by R Longley
NOTES
Geo
ROTI
LTD
THE