

Photo 1.

Illustrating trees located on the embankment below the property.

We understand the tree on the otherside of the footpath is not alive (but I'm not an expert). See photo 2.



Photo 2

Tree on the other side of the footpath (2nd along from right hand side) which we believe is dead (again I'm no tree expert).



Photo 3

Photo taken from boundary fence looking down toward trees and embankment.



Photo 4

Footpath which runs above the tree embankment and below the house.



Photo 5

Photo of the house and footpath



Photo 6

12 Chaucer Close - Footpath to 12 Chaucer Close

