



Reading
Borough Council
Working better with you



Property Services

Project Name: Katesgrove School Simmonds Building, Reading

E04948

Repairs to Timber Windows and External Fabric - Phase 1

Condition Survey photos referenced to the Schedule of Works

Schedule of Works

1.2.3 West Elevation 2 W1



1.2.3

W1



1.2.3

W1



1.2.12 North Elevation 2 W2



1.2.20 West Elevation 2 W12



1.2.24 West Elevation 2 W13 (W14, W13, W12)



1.2.24 W13



1.2.30 W14



1.2.30 W14



1.2.30 W14



1.2.36 North Elevation 2 W15



1.2.42 West Elevation 2 W16



1.2.46 West Elevation 1 W17



1.3.1 North Elevation 2 External Door



1.3.2 West Elevation 2 Dormer Gable



1.4.1, 1.4.2 South Elevation 2 Brickwork and 1.5.3 Downpipes



1.4.3 West Elevation 2 Brickwork W1 Gable



1.4.4 Brickwork W1 Gable – broken string course corner bricks and differential joint weathering



1.4.5 West Elevation 2 Brickwork chimney wall



1.4.6 Door opening arch brickwork repair



1.5.3 Downpipes



1.5.4 North Elevation 2 Single storey gutters and downpipes



1.5.7 Single storey bay gutters & downpipes



1.5.8 Cast iron air bricks

