

Project Name: Katesgrove School Simmonds Building, Reading

E04948

Repairs to Timber Windows and External Fabric - Phase 4

Condition Survey photos referenced to the Schedule of Works

Schedule of Works

4.4 Brickwork East Elevation



4.4.1 -2 East Elevation 1 Brickwork and 4.5.2 Downpipes



4.4.1 Brickwork East Elevation 2 and 4.5.2 Downpipes



4.4.3 North Elevation 1 Brickwork and 4.5.3 Downpipes



4.5.4 - .5 Flat roof gutters and downpipes



4.4.3 North Elevation 1 Brickwork



4.4.4 West Elevation 1 Brickwork, 4.5.4 Gutter, 4.5.6 Downpipes and 4.5.10 CI air bricks



4.4.4 West Elevation 1 Brickwork and 4.5.7 Downpipes



4.5.7 West Elevation 1 Downpipe replacement



4.4.5 West Elevation 1 Brickwork and 4.5.8 -.9 Downpipes



4.5.8 -9 West Elevation 1 Downpipes



4.4.7 West Elevation 1 Brickwork

