



Floor Plans of Work Area
19 Castle Street, Reading, RG1
Listed Building Application

Second Floor works area – Rooms TR15 and TR16




Existing plywood floor lifted to aid drying



Plywood floor to be replaced to match existing

First Floor works area – Front Classroom



Front Classroom ceiling



Front Classroom ceiling





Front classroom wall plaster



Front classroom timber window surround damage


Ground Floor work areas – Rooms TR17 and TR18



Room TR18 ceiling

Room TR18 water damage

Basement works area – Store Area and Kitchen



Basement store area

Kitchen