






-  Planning Application Boundary
-  Long Term Noise Monitoring Locations
-  Sensitive Receptor Locations



Project Details	WIE14788-108: Station Hill, Reading
Figure Title	Figure 11.1: Noise Monitoring and Sensitive Receptor Locations
Figure Ref	WIE14788-108_GR_ES_11.1A
Date	2019
File Location	\\s-incs\wie\projects\wie14788\100\graphics\es\issued figures



Project Details	WIE14788-108: Station Hill, Reading
Figure Title	Figure 13.1: Seasonal Wind Roses for London Heathrow Airport
Figure Ref	WIE14788-108_GR_ES_13.1A
Date	2019
File Location	\\s-Incs\wie\projects\wie14788\100\graphics\esa\issued figures
www.watermangroup.com	



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.2: Configuration 1: Existing Site with the Existing Surrounding Buildings (South Site) – Windiest Season, Ground Level

Figure Ref


WIE14788-108_GR_ES_13.2A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Light Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.3: Configuration 1: Existing Site with the Existing Surrounding Buildings (South Site) – Summer Season, Ground Level

Figure Ref


WIE14788-108_GR_ES_13.3A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.4: Configuration 1: Existing Site with the Existing Surrounding Buildings – Windiest Season, Ground Level

Figure Ref

WIE14788-108_GR_ES_13.4A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Light Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.5: Configuration 1: Existing Site with the Existing Surrounding Buildings – Summer Season, Ground Level

Figure Ref



WIE14788-108_GR_ES_13.5A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading


Figure 13.6: Configuration 1: Existing Site with the Existing Surrounding Buildings – Annual Safety Exceedances, Ground and Terrace Levels

WIE14788-108_GR_ES_13.6A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.7: Configuration 2: South Site with Max Parameter North Site and the Existing Surrounding Buildings – Windiest Season, Ground and Terrace Levels
WIE14788-108_GR_ES_13.7A
2019
\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

Figure Title

Figure Ref

Date

File Location



LEGEND:

LDDC COMFORT CATEGORIES:



Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

Figure Title	WIE14788-108: Station Hill, Reading
Figure Ref	Figure 13.8: Configuration 2: South Site with Max Parameter North Site and the Existing Surrounding Buildings – Summer Season, Ground and Terrace Levels
Date	WIE14788-108_GR_ES_13.8A
File Location	2019
	\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.9: Configuration 2: South Site with Max Parameter North Site and the Existing Surrounding Buildings – Summer Season, Terrace Levels

Figure Ref



WIE14788-108_GR_ES_13.9A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.10: Configuration 2: Interim Development Scenario with the Existing Surrounding Buildings – Windiest Season, Ground and Terrace Levels

Figure Ref


WIE14788-108_GR_ES_13.10A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Light Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.11: Configuration 2: Interim Development Scenario with the Existing Surrounding Buildings – Summer Season, Ground and Terrace Levels

Figure Ref



WIE14788-108_GR_ES_13.11A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading


Figure 13.12: Configuration 2: Interim Development Scenario with the Existing Surrounding Buildings – Annual Safety Exceedances, Ground and Terrace Levels

WIE14788-108_GR_ES_13.12A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.13: Configuration 3: Maximum Parameter Development with the Existing Surrounding Buildings – Windiest Season, Ground and Terrace Levels

Figure Title

Figure Ref



WIE14788-108_GR_ES_13.13A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.14: Configuration 3: Maximum Parameter Development with the Existing Surrounding Buildings – Summer Season, Ground and Terrace Levels

Figure Title

Figure Ref




WIE14788-108_GR_ES_13.14A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

SAFETY CATEGORIES:

- Pass 
- S15 Exceeded 
- S20 Exceeded 

SENSOR LOCATION:

-  Grade Level
-  Podium Level
-  Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.15: Configuration 3: Maximum Parameter Development with the Existing Surrounding Buildings – Annual Safety Exceedances, Ground and Terrace Levels

Figure Ref

WIE14788-108_GR_ES_13.15A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Light Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading

Figure 13.16: Mitigation: South Site with Wind Mitigation Measures, a Max Parameter North Site and the Existing Surrounding Buildings – Windiest Season, Ground and Terrace Levels

WIE14788-108_GR_ES_13.16A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Light Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading



Figure 13.17: Mitigation: South Site with Wind Mitigation Measures, a Max Parameter North Site and the Existing Surrounding Buildings – Summer Season, Ground and Terrace Levels

WIE14788-108_GR_ES_13.17A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading



Figure 13.18: Mitigation: South Site with Wind Mitigation Measures, a Max Parameter North Site and the Existing Surrounding Buildings – Summer Season, Terrace Levels

WIE14788-108_GR_ES_13.18A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.19: Mitigation: Interim Development Scenario with Wind Mitigation Measures and the Existing Surrounding Buildings – Windiest Season, Ground and Terrace Levels

Figure Ref



WIE14788-108_GR_ES_13.19A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.20: Mitigation: Interim Development Scenario with Wind Mitigation Measures and the Existing Surrounding Buildings – Summer Season, Ground and Terrace Levels

Figure Ref



WIE14788-108_GR_ES_13.20A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

SAFETY CATEGORIES:

Pass	
S15 Exceeded	
S20 Exceeded	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.21: Mitigation: Interim Development Scenario with Wind Mitigation Measures and the Existing Surrounding Buildings – Annual Safety Exceedances, Ground and Terrace Levels

Figure Ref

WIE14788-108_GR_ES_13.21A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Light Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.22: Development Option 1 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Windiest Season, Ground and Terrace Levels

Figure Title

Figure Ref


WIE14788-108_GR_ES_13.22A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.23: Development Option 1 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Summer Season, Ground and Terrace Levels

Figure Ref





WIE14788-108_GR_ES_13.23A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:



LDDC COMFORT CATEGORIES:

Activity	Percentage
Sitting	10%
Standing	10%
Strolling	10%
Walking	10%
Uncomfortable	10%

SENSOR LOCATION:

 Grade Level
 Podium Level
 Balcony/Roof Level

Project Details	WIE14788-108: Station Hill, Reading
Figure Title	Figure 13.24: Development Option 1 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Summer Season, Terrace and Balcony Levels
Figure Ref	WIE14788-108_GR_ES_13.24A
Date	2019
File Location	\\s-incs\wie\projects\wie14788\100\graphics\lesa\issued figures



LEGEND:

SAFETY CATEGORIES:

Pass	
S15 Exceeded	
S20 Exceeded	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.25: Development Option 1 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Annual Safety Exceedance, Ground and Terrace Levels

Figure Ref





WIE14788-108_GR_ES_13.25A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

SAFETY CATEGORIES:

Pass	
S15 Exceeded	
S20 Exceeded	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.26: Development Option 1 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Annual Safety Exceedance, Terrace and Balcony Levels

Figure Ref

WIE14788-108_GR_ES_13.26A



Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.27: Development Option 2 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Windiest Season, Ground and Terrace Levels

Figure Title

Figure Ref


WIE14788-108_GR_ES_13.27A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 13.28: Development Option 2 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Summer Season, Ground and Terrace Levels

Figure Ref




WIE14788-108_GR_ES_13.28A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	Green
Standing	Blue
Strolling	Yellow
Walking	Purple
Uncomfortable	Red

SENSOR LOCATION:

Circle	Grade Level
Square	Podium Level
Diamond	Balcony/Roof Level

Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading



Figure 13.29: Development Option 2 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Summer Season, Terrace and Balcony Levels

WIE14788-108_GR_ES_13.29A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

SAFETY CATEGORIES:

Pass	
S15 Exceeded	
S20 Exceeded	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.30: Development Option 2 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Annual Safety Exceedances, Ground and Terrace Levels

Figure Title

Figure Ref




WIE14788-108_GR_ES_13.30A



Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures





LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.32: Development Option 3 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Windiest Season, Ground and Terrace Levels

Figure Title

Figure Ref

WIE14788-108_GR_ES_13.32A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.33: Development Option 3 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Summer Season, Ground and Terrace Levels

Figure Title

Figure Ref





WIE14788-108_GR_ES_13.33A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

LDDC COMFORT CATEGORIES:

Sitting	
Standing	
Strolling	
Walking	
Uncomfortable	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Balcony/Roof Level

Project Details

Figure Title

Figure Ref

Date

File Location




WIE14788-108: Station Hill, Reading
Figure 13.34: Development Option 3 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Summer Season, Terrace and Balcony Levels

WIE14788-108_GR_ES_13.34A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



LEGEND:

SAFETY CATEGORIES:

- Pass 
- S15 Exceeded 
- S20 Exceeded 

SENSOR LOCATION:

-  Grade Level
-  Podium Level
-  Roof Level

Project Details

WIE14788-108: Station Hill, Reading
Figure 13.35: Development Option 3 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Annual Safety Exceedances, Ground and Terrace Levels

Figure Title

Figure Ref





WIE14788-108_GR_ES_13.35A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures



LEGEND:

SAFETY CATEGORIES:

Pass	
S15 Exceeded	
S20 Exceeded	

SENSOR LOCATION:

	Grade Level
	Podium Level
	Roof Level

Project Details

Figure Title

Figure Ref

Date

File Location


WIE14788-108: Station Hill, Reading
Figure 13.36: Development Option 3 with Wind Mitigation Measures and the Cumulative Surrounding Buildings – Annual Safety Exceedances, Terrace and Balcony Levels

WIE14788-108_GR_ES_13.36A


2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures


www.watermangroup.com




Site Boundary




Project Details	WIE14788-108: Station Hill, Reading
Figure Title	Figure 14.1: Daylight Sensitive Receptors
Figure Ref	WIE14788-108_GR_ES_14.1A
Date	2019
File Location	\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures




 Site Boundary



Project Details	WIE14788-108: Station Hill, Reading
Figure Title	Figure 14.2: Sunlight Sensitive Receptors
Figure Ref	WIE14788-108_GR_ES_14.2A
Date	2019
File Location	\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures
www.watermangroup.com	



www.watmangroup.com



Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading


Figure 14.4: Light Pollution Sensitive Receptors

WIE14788-108_GR_ES_14.4A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



Project Details

WIE14788-108: Station Hill, Reading

Figure Title

Figure 14.5: Solar Glare Sensitive Receptors

Figure Ref


WIE14788-108_GR_ES_14.5A

Date

2019

File Location

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures





Source: GIA

© WATERMAN INFRASTRUCTURE & ENVIRONMENT

Reproduced from the Ordnance Survey maps with the permission of the Controller of Her Majesty's Stationery Office, © Crown copyright, Waterman Infrastructure & Environment, Pickfords Wharf, Clink Street, London, SE1 9DG.

Project Details	WIE14788-108: Station Hill, Reading
Figure Title	Figure 14.6: Solar Glare Degrees of Vision
Figure Ref	WIE14788-108_GR_ES_14.6A
Date	2019
File Location	\\s-Incs\wie\projects\wie14788\100\graphics\esa\issued figures
www.watermangroup.com	



Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading


Figure 14.7: Westbound Train Receptor Locations

WIE14788-108_GR_ES_14.7A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com



Project Details

Figure Title

Figure Ref

Date

File Location

WIE14788-108: Station Hill, Reading

Figure 14.8: Eastbound Train Receptor Locations

WIE14788-108_GR_ES_14.8A

2019

\\s-incs\wie\projects\wie14788\100\graphics\esa\issued figures

www.watermangroup.com