



Geotechnical Testing Analysis Report



auger

environmental +
claims mgmt +
subsidence +
drainage +

Unit 3 & 4,
Heol Aur,
Dafen Ind Estate,
Dafen
Llanelli,
Carmarthenshire,
SA14 8QN

**Auger House,
Cross Lane,
Wallasey,
Wirral,
CH45 8RH**

Summary Of Claim Details

Policy Holder	Unknown
Risk Address	Unknown
SI Date	18/02/2019
Issue Date	19/02/2019
Report Date	08/03/2019
Auger Reference	86056.3.2.RSS
Insurance Company	
LA Claim Reference	6846356
LA Co. Reference	Sedgwick International UK

This certificate is issued in accordance with the accreditation requirements of the United Kingdom Accreditation Service. The results reported herein relate only to the material supplied to the laboratory. This certificate shall not be reproduced except in full, without the prior written approval of the laboratory.

	Checked	08/03/2019	Wayne Honey	
	Approved	08/03/2019	Ben Sharp	



GSTL Contract Number	43113	
Risk Address	Unknown	
Auger Reference	86056.3.2.RSS	

[illegible]

Test Operator	Checked	08/03/2019	Wayne Honey	
Conor Davison	Approved	08/03/2019	Ben Sharp	

