

Job Sheet #116505455-776509: VSG GROUP LTD

This job is allocated to SW1

Job Details

CUSTOMER/JOB NAME	CONTACT NAME	ID	STATUS
VSG GROUP LTD	KATHRYN ROSS	1959309	Complete
CONTACT NUMBER	EMAIL	CONTACT NUMBER 2	EMAIL 2
NA	None	NA	None

Timeslot Details

SCHEDULED START	PLANNED DURATION	ACTUAL START	ACTUAL FINISH
2019-25-01 05:56	0 hours, 15 mins	2019-24-01 11:50	2019-24-01 12:43

Job Location/Address UNIT 1 ACRE ROAD READING RG2 0RJ RG2 0RJ

Notes

please install weekly internal and external inspections to the site. NIE07

Skylight window broken	Yes
------------------------	-----

Comments	Multiple leaks
----------	----------------

If yes, location of damage

Front	Yes
-------	-----

Rear	Yes
------	-----

Left side	Yes
-----------	-----

Right side	Yes
------------	-----

Comments	
----------	--

Step 5: External; Gutters, Downpipes

Is there damage to gutters & downpipes?	No damage
---	-----------

Comments	
----------	--

None	Yes
------	-----

Front	No
-------	----

Rear	No
------	----

Left side	No
-----------	----

Right side	No
------------	----

Comments	
----------	--

Step 6: External; Brickwork, Cladding

3rd Gas - Reading 2

Step 19: Water Meter Readings

Water Status Cannot locate

1st Water - Location

1st Water - Serial Number

1st Water - Reading

2nd Water - Serial Number

2nd Water - Location

2nd Water - Reading

Step 20: Flooding

Any sign of water ingress from roof/ceiling (leaks) Yes

Comments Multiple warehouse minor 1st floor

Any sign of flooding? Considerable

Comments Reception

If yes, location of damage

Basement No

Bathroom No

Kitchen No


Ground Floor Yes



Taken 2019-24-01 12:24



Taken 2019-24-01 12:25




Taken 2019-24-01 12:26



Taken 2019-24-01 12:26



Taken 2019-24-01 12:27



Taken 2019-24-01 12:27 (Electric)