



GEOSHIELD Verification Report



PROJECT REFERENCE: GEO1001700/KC/P

PROJECT: Porcelenosa: Kenwood Construction

PROJECT ADDRESS: 21 Rose Kiln Lane

Reading

RG1 6SP

MEMBRANE SPECIFICATION: Gas membrane to specification BS8485 2015

Installed to CIRIA 735

Hydroprufe 9000

Hydroprufe 8000

Dual Tape

Girth Tape

Foil backed detailing tape

Hydroprufe LG Liquid Gas Membrane

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



MEMBRANE SPECIFICATION:

DESIGN DETAILS:

31363/5002/003 C1 Foundations and ground floor plan

31363/5002/020 C2 Substructure Sections

365001 Rev A

365002 Rev A

365003 Rev A

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



SURVEYOR:

Chris Kynman

VERIFICATION COMPANY:

GeoShield Limited

Hoyle Mill Road

Kinsley

West Yorkshire

WF9 5JB

CONTACT NUMBER:

07387 373 167

EMAIL ADDRESS:

Chris.kynman@geoshield.co.uk

ORDER NUMBER:

PER VISIT: YES:

☐

NO:

☐

PROJECT: YES:



NO:

☐

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



CLIENT DETAILS

CLIENT CONTACT: Stephen Gatehouse

CONTACTS ROLE: Project Manager

MOBILE PHONE:

EMAIL ADDRESS:

CLIENT CONTACT:

CONTACTS ROLE:

MOBILE PHONE:

EMAIL ADDRESS

NOTES:

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



APPLICATION TEAM LEADERS

APPLICATOR NAME: Tony Groves: Foreman

COMPANY: Nick Kenward Construction Limited

APPLICATOR TEL: 07730 575862

APPLICATOR EMAIL:

APPLICATOR NAME: Frank Holman

COMPANY: Nick Kenward Construction Limited

APPLICATOR TEL: 07917 688078

APPLICATOR EMAIL:

NOTES:

NOTES:

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



AREA SURVEYED: Area: A/H - 1/3+

Floor slab

SITE CONDITIONS:

WEATHER: Overcast

TEMPERATURE: 10C

MEMBRANE TEMPERATURE: N/A

RELATIVE HUMIDITY: 63%

TIME: 8.30am- 1.00pm REPORT NUMBER: 001

DATE: 20th February 2017


ACCOMPANIED Tony Groves

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.

GEOSHIELD Verification Report

VERIFICATION LAYOUT



Area: A/H - 1/3+



GEOSHIELD Verification Report



OVERVIEW PHOTOS



Sand blinding looking to H - 2

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



OVERVIEW PHOTOS



View to A1 corner

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA:

Area: A/H - 1/3+

RESTRICTIONS AND LIMITATIONS:

All applications were available for Verification

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA:

N/A

RESTRICTIONS AND LIMITATIONS:

No limitations or restrictions

Click to set image

Click to set image

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE

LOCATION/GRID LINE: Grid Line: A/H - 1

NOTES:

Application of Hydroprufe LG, 2 coats

Junction between ground beam and blinding: taped using girth tape.



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed


Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM ONE



Junction between ground beam and blinding: taped using girth tape.

Hydroprufe LG can also be clearly seen applied to specification

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM TWO

LOCATION/GRID LINE: Area: A/H - 1/3+

NOTES: General Application

Sand blinding to Specification

Dual tape



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM TWO



Girth Tape

View from D1 to H2

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report




VERIFICATION ITEM THREE

LOCATION/GRID LINE: Area: A/H - 1/3+

NOTES: Detailing work

Pipe Penetration

Edge beam detail



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed


Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



VERIFICATION ITEM THREE



300mm wide Detailing strip to seal Membrane to edge beam

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.



GEOSHIELD Verification Report



REMEDIATION LOG

Date	Nr	Remediation Description	Y/N
20th Mar	001	No remediation items	✓
20th Mar	001	Protection board still to fix	




GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed





GEOSHIELD Verification Report



ADDITIONAL PHOTOS



Additional GR Primer



GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



GAS MEMBRANE TESTING

VISUAL:	☐ YES	☒	☐ NO	☐	SMOKE TEST:	☐ YES	☐	☐ NO	☐
COMPRESSED AIR:	☐ YES	☐	☐ NO	☐	DILECTIC	☐ YES	☐	☐ NO	☐
DESTRUCTIVE:	☐ YES	☒	☐ NO	☐		☐ YES	☐	☐ NO	☐
OTHER:									

GRID LINE:	Area: A/H - 1/3+	☐
GRID LINE:		☐
GRID LINE:		☐
GRID LINE:		☐
GRID LINE:		☐
GRID LINE:		☐
GRID LINE:		☐
GRID LINE:		☐
GRID LINE:		☐
GRID LINE:		☐

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed



GEOSHIELD Verification Report



VERIFICATION SUMMARY

Internal vertical faces applied to Premcrete specification

Some minor remediations in the process of being completed

GEOSHIELD SIGNITURE:

DATE: 8th February 2017

GeoShield Ltd gives no representations or warranties, express or implied and no responsibility or liability is accepted for the accuracy or completeness of the information inserted in the document or any other written or oral information given to any interested party or its advisers. Any such liability is expressly disclaimed

Verification Plan will not be legally valid until payment is made.