

Appendix B Field reconnaissance photographs

Desk Study Photograph 1	
Date: 12/01/23	
Direction Photograph Taken: Looking west along southern boundary.	
Description: Existing derelict building	

Desk Study Photograph 2	
Date: 12/01/23	
Direction Photograph Taken: Looking northwest.	
Description: Existing derelict building and site entrance gate.	

Desk Study Photograph 3	
Date: 12/01/23	
Direction Photograph Taken: Looking south towards site entrance.	
Description: Existing bund blocking vehicle access to the site.	

Desk Study Photograph 4	
Date: 12/01/23	
Direction Photograph Taken: Looking north along eastern boundary.	
Description: Existing trees in soft landscaping and existing derelict building.	

Desk Study Photograph 5	
Date: 12/01/23	
Direction Photograph Taken: Looking northeast.	
Description: Northeast corner of the site.	

Desk Study Photograph 6	
Date: 12/01/23	
Direction Photograph Taken: Looking west along northern boundary.	
Description: Overhead lines and derelict building.	

Desk Study Photograph 7	
Date: 12/01/23	
Direction Photograph Taken: Looking west.	
Description: Access to garden areas.	

Desk Study Photograph 8	
Date: 12/01/23	
Direction Photograph Taken: Looking north.	
Description: Overgrown area of garden.	

Desk Study Photograph 9	
Date: 12/01/23	
Direction Photograph Taken: Looking north.	
Description: Main Garden area.	