

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point


Risk of Flooding from Surface Water

- High - 30 Year Return
- Medium - 100 Year Return
- Low - 1000 Year Return

Suitability

- See the suitability map below
- National to county
 - County to town
 - Town to street
 - Street to parcels of land
 - Property

E/NRW Suitability Map - Slice A





Order Details

Order Number: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road,
READING, RG2 7DE





Geotechnical & Environmental Consultants

WFD Surface Waters Map

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID


Water Framework Directive - Surface Water Quality

- High
- Good
- Moderate
- Poor
- Bad

Contours (height in meters)

- Standard Contour
- Master Contour
- Spot Height
- Mean Low Water
- Mean High Water

WFD Surface Waters Map - Slice A



Order Details


Order Number: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road, READING, RG2 7DE



Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk




General


- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Estimated Soil Chemistry Arsenic

Arsenic Concentrations mg/kg



Estimated Soil Chemistry Arsenic - Slice A



Order Details


Order Details: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road,
READING, RG2 7DE



Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk




General


- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Estimated Soil Chemistry Cadmium

Cadmium Concentrations mg/kg



Estimated Soil Chemistry Cadmium - Slice A



Order Details


Order Details: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road,
READING, RG2 7DE



Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk




General


Specified Site Specified Buffer(s) Bearing Reference Point

Estimated Soil Chemistry Chromium

Chromium Concentrations mg/kg



Estimated Soil Chemistry Chromium - Slice A



Order Details


Order Details: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road,
READING, RG2 7DE



Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and database rights 2024 OS AC0000813445




General


- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Estimated Soil Chemistry Lead

Lead Concentrations mg/kg



Estimated Soil Chemistry Lead - Slice A



Order Details

Order Details: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road,
READING, RG2 7DE




Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

General


Specified Site Specified Buffer(s) Bearing Reference Point

Estimated Soil Chemistry Nickel

Nickel Concentrations mg/kg



Estimated Soil Chemistry Nickel - Slice A




Order Details

Order Details: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road,
READING, RG2 7DE



soils
LIMITED
Geotechnical & Environmental
Consultants

Ground Stability Data (1:50,000)

General

-  Specified Site
  Specified Buffer(s)
  Bearing Reference Point
 Slice
 Map ID

Potential for Compressible Ground Stability Hazards

- | | | | |
|---|----------|---|----------|
|  | High |  | Low |
|  | Moderate |  | Very Low |


Potential for Collapsible Ground Stability Hazards

-  High
  Low
-  Moderate
  Very Low

Brine Pumping and Salt Mining

- Brine Pumping Related Feature  
- Salt Mining Related Feature  

Mining and Ground Stability - Slice A



Order Details


Order Number:	361237522_1_1
Customer Ref:	21640
National Grid Reference:	473480, 171270
Slice:	A
Site Area (Ha):	0.85
Search Buffer (m):	1000

Site Details

Grove House, Leighton Park School, Shinfield Road, READING, RG2 7DE

Landmark®
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and database rights 2024 OS AC0000613445



Ground Stability Data (1:50,000)

General

- ◇ Specified Site ○ Specified Buffer(s) X Bearing Reference Point
- Slice B Map ID


Potential for Landslide Ground Stability Hazards

- High ■ Low
- Moderate ■ Very Low

Potential for Ground Dissolution Stability Hazards

- ▨ High ▨ Low
- ▨ Moderate ▨ Very Low

Mining and Ground Stability - Slice A



Order Details

Order Number: 361237522_1_1
 Customer Ref: 21640
 National Grid Reference: 473480, 171270
 Slice: A
 Site Area (Ha): 0.85
 Search Buffer (m): 1000


Site Details

Grove House, Leighton Park School, Shinfield Road, READING, RG2 7DE



Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk

471500 472000 472500 473000 473500 474000 474500 475000 475500



© Crown copyright and database rights 2024 OS AC0000613445

0 1 km



Ground Stability Data (1:50,000)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID


Potential for Running Sand Ground Stability Hazards

- High
- Moderate
- Low
- Very Low

Potential for Shrinking or Swelling Clay Ground Stability Hazards

- High
- Moderate
- Low
- Very Low

Mining and Ground Stability - Slice A



Order Details

Order Number: 361237522_1_1
Customer Ref: 21640
National Grid Reference: 473480, 171270
Slice: A
Site Area (Ha): 0.85
Search Buffer (m): 1000

Site Details

Grove House, Leighton Park School, Shinfield Road, READING, RG2 7DE



Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk