



Key

- Site Boundary
- Validation Pit Locations (HP)
(HP1 - HP11)
- Tank Location

enzygo
environmental consultants

Samuel House, 5 Fox Valley Way, Stocksbridge, Sheffield, S36 2AA

CLIENT: Bellway Homes		
SCALE: 1:500@A3	PROJECT REF: CRM.1265.035	
DRAWN: LB	CHECKED: SR	DATE: July 2023
PROJECT: Dee Road, Reading		
TITLE: Remediation Plan		
FIGURE NO: CRM.1265.035.GE.D.002		